OK

Depth 6	Contents 7	Reference to last Measurement 8
railway marking		
Super Sly Cpwk		
Cross Wall		
90	27·00	
90	27·90	
90	27·00	
90	27·00	
90	27·00	
90	28·20	
90	27·00	
90	29·70	
90	27·00	
90	19·80	423360
	264·60 Sqm	

Audited and admitted Rs. 2186132=00
Passed by Chief Engineer Rs. 1910300=00

M. A. R. 57 (Rule 116)
Measurement Book

Serial No. .....
Name of work ..... From ..... To .....
Name of Contractor or nature of Agency.....
Date of commencement of work.....

Nineteen Lakhs Ten Thousand Three hundred only

275832=00

82714

Item	Full description, etc. of work	Number	Dimensions: Length	Breadth	Depth	Contents	Reference to last Measurement
	2	3	4	5	6	7	8
7	Disposal of debris to a dump place as directed by the Engineer by present recorded vide Certificate				Disposal with all lead and lift @ 78.24/cum	352·80 cum	27603/—
(1)	work done is satisfactory					Total	199752=00
(2)	There are no deportments / Errors made to the Contract		Held 10 d. T.P.			198739=00	199752=00
(3)	Contractor has cleared all debris from the work site.					198739=00	197274=00
						2186132=00	

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಸುಂಕದಕಟ್ಟೆ, ಬೆಂಗಳೂರು - 560 073